

<b>FIRMWARE - RELEASE</b>								<b>NO.: SR-800801.11</b>			
<b>General Information:</b>					<b>Affected File(s):</b>						
<b>Software-Number:</b> miscellaneous					<b>ProductVersion:</b>						
<b>Last released Version:</b> 26102021					- 07051121.010002.020510						
<b>New Version:</b> For new versions see right side Internal named "Version 29032022"					<b>dts4138app.img</b>						
<b>Release Date:</b> 06.10.2022					- dts4138app 204900 V1.06.0000						
<b>Software Author:</b> hjr					- timedev 204902 V0.03.0000						
<b>Affected Products:</b> DTS 4138.timeserver					- ntp 204908 V4.2.8p14.005						
<b>Product-Number(s):</b> 204760, 205280, 117982, 117981					- dts-snmpd 204906 V1.01.0000						
<b>Release by Software Developer:</b>					- Language0.res V0.07						
<b>This signature validates the release:</b>					- Language1.res V0.07						
<b>Modifications, Improvements:</b>					<b>dts4138v2cfg.img</b>						
-Fix: Sync adjust from NTP was very slow -> improved					- timezone table: moba 0010						
-Fix: NTP did not reach stratum 16 in any case					user 0001						
<b>Reason for Modification, Impro.:</b>					<b>rootfsDTS4138.img (204911)</b>						
-					- Built 051121.100247						
<b>Recommendation for Update:</b>					- Busybox 204910 V1.31.1.0001						
					- snmpd 204905 V5.8.0.0000						
<b>Procedure for Update:</b>					<b>u-bootDTS4138</b>						
<b>Update 26102021 has to be done first!</b>					- bootloader 204909 V2013.07						
See also Bx-800870.10 or higher: chapter 7.					<b>ulmageDTS4138</b>						
<b>Remarks, Enclosures:</b>					- kernel 204904 V3.2.3.0007						
<b>Vom Entwickler auszufüllen:</b>					<b>OK N/A</b>		<b>OK N/A</b>				
- Prüfsystem kompatibel mit neuer Firmware:					<input checked="" type="checkbox"/> <input type="checkbox"/>		- Versionsanpassung komplettes Gerät nötig?:		<input type="checkbox"/> <input checked="" type="checkbox"/>		
- Neue Firmware in Produktions-Verzeichnis verfügbar:					<input checked="" type="checkbox"/> <input type="checkbox"/>		- Version angepasst:		<input checked="" type="checkbox"/> <input type="checkbox"/>		
- Neue Firmware in Sales-Verzeichnis verfügbar:					<input checked="" type="checkbox"/> <input type="checkbox"/>		- Source Code gesichert:		<input checked="" type="checkbox"/> <input type="checkbox"/>		
- Updateprozess auf Gerät getestet:					<input checked="" type="checkbox"/> <input type="checkbox"/>		- Dokumentationsanpassung definiert:		<input checked="" type="checkbox"/> <input type="checkbox"/>		
<b>Distribution</b>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input type="checkbox"/>		<input checked="" type="checkbox"/>		<input type="checkbox"/>	
PositionE		E →		EL →		AVOR →		CSO →		E →	
Name		.....		HJ. Rohrer		.....		.....		.....	
Date											
Signature										Filing: A. Kohler	
										Support → External: <input type="checkbox"/> Verkaufsgesellschaften	

Anweisung zu Verteilung und Ablage: Das Dokument wird in der Regel per interne Post (Lauffeiste) an die verschiedenen Stellen gesandt und von jeder Stelle datiert und visiert. Das Dokument wird erst datiert und weitergeleitet, wenn die oben verlangten Aktionen ausgeführt sind. Zur Ablage im DMS und Information der Verkaufsstellen soll das Dokument direkt per E-Mail an AK gesandt werden.  
Die Freigabe der Firmware erfolgt gemäss AA-952003 Softwareentwicklung Kap. „Behandlung Firmwares in der Produktion.“